

Pipe Graphic Report of
Database: POUGHKEEPSIE 2017-2018.mdb

PO #

Sheet # 36
Surveyor MANNY (07003732)
Street HAIGHT AVE
City POUGHKEEPSIE
Further Loc. Details

Owner

Date 20171018 08:10
Drainage

Upstream MH 108 **Rim-Invert** 0.0 ft **Grade-Invert** 0.0 ft **Rim-Grade** 0.0 ft
Downstream MH 107 **Rim-Invert** 0.0 ft **Grade-Invert** 0.0 ft **Rim-Grade** 0.0 ft


Use **Direction** Downstream **Joint Length** **Height** 8 in **Width**
Shape Circular **Flow Control** **Total Length** **Year Laid**
Material Clay Tile **Pre Cleaning** Jetting **Surveyed** 55.4 ft **Year Rehab**
Lining **Weather** **Purpose**
Location **Category**
Media/Tape # **Pressure**
Northing **Easting** **Elevation**
GPS Accuracy **Coordinate System**

Additional Info

Work Order

Project

DVS File C:\Users\Preferred Customer\Documents\My Muni Data\POUGHKEEPSIE 2017-2018\MH 108_MH 107_171018_36.wmv



Pipe Graphic Report of
Database: POUGHKEEPSIE 2017-2018.mdb

PO #

Sheet # 37
Surveyor MANNY (07003732)
Street HAIGHT AVE
City POUGHKEEPSIE
Further Loc. Details

Owner

Date 20171018 08:45
Drainage

Upstream MH 108 **Rim-Invert** 0.0 ft **Grade-Invert** 0.0 ft **Rim-Grade** 0.0 ft
Downstream MH 107 **Rim-Invert** 0.0 ft **Grade-Invert** 0.0 ft **Rim-Grade** 0.0 ft


Use **Direction** Downstream **Joint Length** **Height** 8 in **Width**
Shape Circular **Flow Control** **Total Length** **Year Laid**
Material Clay Tile **Pre Cleaning** Jetting **Surveyed** 126.9 ft **Year Rehab**
Lining **Weather** **Purpose**
Location **Category**
Media/Tape # **Pressure**
Northing **Easting** **Elevation**
GPS Accuracy **Coordinate System**

Additional Info

Work Order

Project

DVS File C:\Users\Preferred Customer\Documents\My Muni Data\POUGHKEEPSIE 2017-2018\MH 108_MH 107_171018_37.wmv



Pipe Graphic Report of
Database: POUGHKEEPSIE 2017-2018.mdb

PO #

Sheet # 50
Surveyor MANNY (07003732)
Street US-44
City POUGHKEEPSIE
Further Loc. Details

Owner

Date 20171018 14:47
Drainage

Upstream MH 138 **Rim-Invert** 0.0 ft **Grade-Invert** 0.0 ft **Rim-Grade** 0.0 ft
Downstream MH 137 **Rim-Invert** 0.0 ft **Grade-Invert** 0.0 ft **Rim-Grade** 0.0 ft


Use **Direction** Downstream **Joint Length** **Height** 8 in **Width**
Shape Circular **Flow Control** **Total Length** **Year Laid**
Material Clay Tile **Pre Cleaning** Jetting **Surveyed** 246.6 ft **Year Rehab**
Lining **Weather** **Purpose**
Location **Category**
Media/Tape # **Pressure**
Northing **Easting** **Elevation**
GPS Accuracy **Coordinate System**

Additional Info

Work Order

Project

DVS File C:\Users\Preferred Customer\Documents\My Muni Data\POUGHKEEPSIE 2017-2018\MH 138_MH 137_171018_50.wmv



Pipe Graphic Report of
Database: POUGHKEEPSIE 2017-2018.mdb

PO #

Sheet # 51
Surveyor MANNY (07003732)
Street US-44
City POUGHKEEPSIE
Further Loc. Details

Owner

Date 20171018 15:10
Drainage

Upstream MH 138 **Rim-Invert** 0.0 ft **Grade-Invert** 0.0 ft **Rim-Grade** 0.0 ft
Downstream MH 137 **Rim-Invert** 0.0 ft **Grade-Invert** 0.0 ft **Rim-Grade** 0.0 ft


Use **Direction** Downstream **Joint Length** **Height** 8 in **Width**
Shape Circular **Flow Control** **Total Length** **Year Laid**
Material Clay Tile **Pre Cleaning** Jetting **Surveyed** 325.3 ft **Year Rehab**
Lining **Weather** **Purpose**
Location **Category**
Media/Tape # **Pressure**
Northing **Easting** **Elevation**
GPS Accuracy **Coordinate System**

Additional Info

Work Order

Project

DVS File C:\Users\Preferred Customer\Documents\My Muni Data\POUGHKEEPSIE 2017-2018\MH 138_MH 137_171018_51.wmv



Pipe Graphic Report of
Database: POUGHKEEPSIE CLEAN AND CCTV 2017.mdb

PO #

Sheet # 184 **Owner**
Surveyor RICH (1114-06022759)
Street LOCUST RD
City POUGHKEEPSIE
Further Loc. Details

Date 20171011 12:03
Drainage

Upstream MH 196 ROOT CUT **Rim-Invert** 0.0 ft **Grade-Invert** 0.0 ft **Rim-Grade** 0.0 ft
Downstream MH 195 ROOT CUT **Rim-Invert** 0.0 ft **Grade-Invert** 0.0 ft **Rim-Grade** 0.0 ft


Use **Direction** Upstream **Joint Length** **Height** 8 in **Width**
Shape Circular **Flow Control** **Total Length** **Year Laid**
Material Vitrified Clay Pipe **Pre Cleaning** Jetting **Surveyed** 345.4 ft **Year Rehab**
Lining **Weather** **Purpose**
Location **Category**
Media/Tape # **Pressure**
Northing **Easting** **Elevation**
GPS Accuracy **Coordinate System**

Additional Info

Work Order

Project

DVS File C:\ Users\ Preferred Customer\ Documents\ My Muni Data\ POUGHKEEPSIE CLEAN AND CCTV 2017\
 MH 196 ROOT CUT_MH 195 ROOT CUT_171011_184.wmv



Pipe Graphic Report of
Database: POUGHKEEPSIE CLEAN AND CCTV 2017.mdb

PO #

Sheet # 185
Owner
Surveyor MANNY (07003732)
Street WING RD
City POUGHKEEPSIE
Further Loc. Details

Date 20170808 08:36
Drainage


Upstream MH 200 ROOT CUT **Rim-Invert** 0.0 ft **Grade-Invert** 0.0 ft **Rim-Grade** 0.0 ft
Downstream MH 195 ROOT CUT **Rim-Invert** 0.0 ft **Grade-Invert** 0.0 ft **Rim-Grade** 0.0 ft

Use **Direction** Upstream **Joint Length** **Height** 8 in **Width**
Shape Circular **Flow Control** **Total Length** **Year Laid**
Material Clay Tile **Pre Cleaning** Jetting **Surveyed** 35.3 ft **Year Rehab**
Lining **Weather** **Purpose**
Location **Category**
Media/Tape # **Pressure**
Northing **Easting** **Elevation**
GPS Accuracy **Coordinate System**

Additional Info

Work Order **Project**

DVS File C:\ Users\ Preferred Customer\ Documents\ My Muni Data\ POUGHKEEPSIE CLEAN AND CCTV 2017\
 MH 200_MH 195_170808_185.wmv



Pipe Graphic Report of
Database: POUGHKEEPSIE CLEAN AND CCTV 2017.mdb

PO #

Sheet # 49 **Owner**
Surveyor RICH (1114-06022759)
Street LOCUST RD
City POUGHKEEPSIE
Further Loc. Details

Date 20170626 15:14
Drainage

Upstream MH196 **Rim-Invert** 0.0 ft **Grade-Invert** 0.0 ft **Rim-Grade** 0.0 ft
Downstream MH 195 **Rim-Invert** 0.0 ft **Grade-Invert** 0.0 ft **Rim-Grade** 0.0 ft


Use **Direction** Upstream **Joint Length** **Height** 8 in **Width**
Shape Circular **Flow Control** **Total Length** **Year Laid**
Material Vitrified Clay Pipe **Pre Cleaning** Jetting **Surveyed** 83.7 ft **Year Rehab**
Lining **Weather** **Purpose**
Location **Category**

Media/Tape # **Pressure**
Northing **Easting** **Elevation**
GPS Accuracy **Coordinate System**

Additional Info

Work Order **Project**

DVS File C:\ Users\ Preferred Customer\ Documents\ My Muni Data\ POUGHKEEPSIE CLEAN AND CCTV 2017\
 MH196_MH 195_170626_49.wmv



Pipe Graphic Report of
Database: POUGHKEEPSIE CLEAN AND CCTV 2017.mdb

PO #

Sheet # 48
Owner
Surveyor RICH (1114-06022759)
Street WING RD
City POUGHKEEPSIE
Further Loc. Details

Date 20170626 14:40
Drainage

Upstream MH 200 **Rim-Invert** 0.0 ft **Grade-Invert** 0.0 ft **Rim-Grade** 0.0 ft
Downstream MH195 **Rim-Invert** 0.0 ft **Grade-Invert** 0.0 ft **Rim-Grade** 0.0 ft


Use **Direction** Downstream **Joint Length** **Height** 8 in **Width**
Shape Circular **Flow Control** **Total Length** **Year Laid**
Material Vitrified Clay Pipe **Pre Cleaning** Jetting **Surveyed** 373.5 ft **Year Rehab**
Lining **Weather** **Purpose**
Location **Category**
Media/Tape # **Pressure**
Northing **Easting** **Elevation**
GPS Accuracy **Coordinate System**

Additional Info

Work Order

Project

DVS File C:\Users\Preferred Customer\Documents\My Muni Data\POUGHKEEPSIE CLEAN AND CCTV 2017\
 MH 200_MH195_170626_48.wmv



Pipe Graphic Report of
Database: POUGHKEEPSIE 2017-2018.mdb

PO #

Sheet # 20
Owner
Surveyor MANNY (07003732)
Street MANCHESTER CIRCLE
City POUGHKEEPSIE
Further Loc. Details

Date 20171013 12:17
Drainage

Upstream MH 218 **Rim-Invert** 0.0 ft **Grade-Invert** 0.0 ft **Rim-Grade** 0.0 ft
Downstream MH 217 **Rim-Invert** 0.0 ft **Grade-Invert** 0.0 ft **Rim-Grade** 0.0 ft


Use **Direction** Upstream **Joint Length** **Height** 8 in **Width**
Shape Circular **Flow Control** **Total Length** **Year Laid**
Material Clay Tile **Pre Cleaning** Jetting **Surveyed** 101.1 ft **Year Rehab**
Lining **Weather** **Purpose**
Location **Category**
Media/Tape # **Pressure**
Northing **Easting** **Elevation**
GPS Accuracy **Coordinate System**

Additional Info

Work Order

Project

DVS File C:\Users\Preferred Customer\Documents\My Muni Data\POUGHKEEPSIE 2017-2018\MH 218_MH 217_171013_20.wmv



Pipe Graphic Report of
Database: POUGHKEEPSIE 2017-2018.mdb

PO #

Sheet # 19
Owner
Surveyor MANNY (07003732)
Street MANCHESTER CIRCLE
City POUGHKEEPSIE
Further Loc. Details

Date 20171013 12:17
Drainage

Upstream MH 218 **Rim-Invert** 0.0 ft **Grade-Invert** 0.0 ft **Rim-Grade** 0.0 ft
Downstream MH 217 **Rim-Invert** 0.0 ft **Grade-Invert** 0.0 ft **Rim-Grade** 0.0 ft


Use **Direction** Downstream **Joint Length** **Height** 8 in **Width**
Shape Circular **Flow Control** **Total Length** **Year Laid**
Material Clay Tile **Pre Cleaning** Jetting **Surveyed** 70.5 ft **Year Rehab**
Lining **Weather** **Purpose**
Location **Category**
Media/Tape # **Pressure**
Northing **Easting** **Elevation**
GPS Accuracy **Coordinate System**

Additional Info

Work Order

Project

DVS File C:\Users\Preferred Customer\Documents\My Muni Data\POUGHKEEPSIE 2017-2018\MH 218_MH 217_171013_19.wmv



Pipe Graphic Report of
Database: POUGHKEEPSIE 2017-2018.mdb

PO #

Sheet # 7
Owner
Surveyor MANNY (07003732)
Street MEADOW RD
City POUGHKEEPSIE
Further Loc. Details

Date 20171012 10:08
Drainage

Upstream MH 221 **Rim-Invert** 0.0 ft **Grade-Invert** 0.0 ft **Rim-Grade** 0.0 ft
Downstream MH 213 **Rim-Invert** 0.0 ft **Grade-Invert** 0.0 ft **Rim-Grade** 0.0 ft


Use **Direction** Downstream **Joint Length** **Height** 8 in **Width**
Shape Circular **Flow Control** **Total Length** **Year Laid**
Material Clay Tile **Pre Cleaning** Jetting **Surveyed** 393.5 ft **Year Rehab**
Lining **Weather** **Purpose**
Location **Category**
Media/Tape # **Pressure**
Northing **Easting** **Elevation**
GPS Accuracy **Coordinate System**

Additional Info

Work Order

Project

DVS File C:\Users\Preferred Customer\Documents\My Muni Data\POUGHKEEPSIE 2017-2018\MH 221_MH 213_171012_7.wmv



Pipe Graphic Report of
Database: POUGHKEEPSIE 2017-2018.mdb

PO #

Sheet # 7
Owner
Surveyor MANNY (07003732)
Street MEADOW RD
City POUGHKEEPSIE
Further Loc. Details

Date 20171012 10:08
Drainage

Upstream MH 221 **Rim-Invert** 0.0 ft **Grade-Invert** 0.0 ft **Rim-Grade** 0.0 ft
Downstream MH 213 **Rim-Invert** 0.0 ft **Grade-Invert** 0.0 ft **Rim-Grade** 0.0 ft


Use **Direction** Downstream **Joint Length** **Height** 8 in **Width**
Shape Circular **Flow Control** **Total Length** **Year Laid**
Material Clay Tile **Pre Cleaning** Jetting **Surveyed** 393.5 ft **Year Rehab**
Lining **Weather** **Purpose**
Location **Category**
Media/Tape # **Pressure**
Northing **Easting** **Elevation**
GPS Accuracy **Coordinate System**

Additional Info

Work Order

Project

DVS File C:\Users\Preferred Customer\Documents\My Muni Data\POUGHKEEPSIE 2017-2018\MH 221_MH 213_171012_7.wmv



Pipe Graphic Report of
Database: POUGHKEEPSIE CLEAN AND CCTV 2017.mdb

PO #

Sheet # 191
Surveyor MANNY (07003732)
Street OVEROCKER RD
City POUGHKEEPSIE
Further Loc. Details

Owner

Date 20171016 11:51
Drainage

Upstream MH 27A **Rim-Invert** 0.0 ft **Grade-Invert** 0.0 ft **Rim-Grade** 0.0 ft
Downstream MH 233 **Rim-Invert** 0.0 ft **Grade-Invert** 0.0 ft **Rim-Grade** 0.0 ft

Use **Direction** Upstream **Joint Length** **Height** 8 in **Width**
Shape Circular **Flow Control** **Total Length** **Year Laid**
Material Clay Tile **Pre Cleaning** Jetting **Surveyed** 268.4 ft **Year Rehab**
Lining **Weather** **Purpose**
Location **Category**
Media/Tape # **Pressure**
Northing **Easting** **Elevation**
GPS Accuracy **Coordinate System**


Additional Info

Work Order

Project

DVS File

C:\Users\Preferred Customer\Documents\My Muni Data\POUGHKEEPSIE CLEAN AND CCTV 2017\
 MH 27A_MH 233_171016_191.wmv



Pipe Graphic Report of
Database: POUGHKEEPSIE CLEAN AND CCTV 2017.mdb

PO #

Sheet # 134
Surveyor MANNY (07003732)
Street MOUNTAIN VIEW RD
City POUGHKEEPSIE
Further Loc. Details

Owner

Date 20170720 08:59
Drainage

Upstream MH 244 **Rim-Invert** 0.0 ft **Grade-Invert** 0.0 ft **Rim-Grade** 0.0 ft
Downstream MH 243B **Rim-Invert** 0.0 ft **Grade-Invert** 0.0 ft **Rim-Grade** 0.0 ft


Use **Direction** Downstream **Joint Length** **Height** 8 in **Width**
Shape Circular **Flow Control** **Total Length** **Year Laid**
Material Clay Tile **Pre Cleaning** Jetting **Surveyed** 130.8 ft **Year Rehab**
Lining **Weather** **Purpose**
Location **Category**
Media/Tape # **Pressure**
Northing **Easting** **Elevation**
GPS Accuracy **Coordinate System**

Additional Info

Work Order

Project

DVS File C:\Users\Preferred Customer\Documents\My Muni Data\POUGHKEEPSIE CLEAN AND CCTV 2017\
 MH 244_MH 243B_170720_134.wmv



Pipe Graphic Report of
Database: POUGHKEEPSIE CLEAN AND CCTV 2017.mdb

PO #

Sheet # 144
Owner
Surveyor MANNY (07003732)
Street DUROCHER TERRACE
City POUGHKEEPSIE
Further Loc. Details

Date 20170731 09:35
Drainage


Upstream MH 262 **Rim-Invert** 0.0 ft **Grade-Invert** 0.0 ft **Rim-Grade** 0.0 ft
Downstream MH 261 **Rim-Invert** 0.0 ft **Grade-Invert** 0.0 ft **Rim-Grade** 0.0 ft

Use **Direction** Upstream **Joint Length** **Height** 8 in **Width**
Shape Circular **Flow Control** **Total Length** **Year Laid**
Material Clay Tile **Pre Cleaning** Jetting **Surveyed** 28.4 ft **Year Rehab**
Lining **Weather** **Purpose**
Location **Category**
Media/Tape # **Pressure**
Northing **Easting** **Elevation**
GPS Accuracy **Coordinate System**

Additional Info

Work Order **Project**

DVS File C:\Users\Preferred Customer\Documents\My Muni Data\POUGHKEEPSIE CLEAN AND CCTV 2017\MH 262_MH 261_170731_144.wmv



Pipe Graphic Report of
Database: POUGHKEEPSIE CLEAN AND CCTV 2017.mdb

PO #

Sheet # 143 **Owner**
Surveyor MANNY (07003732)
Street DUROCHER TERRACE
City POUGHKEEPSIE
Further Loc. Details

Date 20170731 09:35
Drainage

Upstream MH 262 **Rim-Invert** 0.0 ft **Grade-Invert** 0.0 ft **Rim-Grade** 0.0 ft
Downstream MH 261 **Rim-Invert** 0.0 ft **Grade-Invert** 0.0 ft **Rim-Grade** 0.0 ft

Use **Direction** Downstream **Joint Length** **Height** 8 in **Width**
Shape Circular **Flow Control** **Total Length** **Year Laid**
Material Clay Tile **Pre Cleaning** Jetting **Surveyed** 99.4 ft **Year Rehab**
Lining **Weather** **Purpose**
Location **Category**
Media/Tape # **Pressure**
Northing **Easting** **Elevation**
GPS Accuracy **Coordinate System**

Additional Info

Work Order **Project**

DVS File C:\Users\Preferred Customer\Documents\My Muni Data\POUGHKEEPSIE CLEAN AND CCTV 2017\
 MH 262_MH 261_170731_143.wmv



Pipe Graphic Report of
Database: POUGHKEEPSIE CLEAN AND TV 2016.mdb

PO #

Sheet # 128
Owner
Surveyor MANNY (07003732)
Street SEITZ TERRACE
City POUGHKEEPSIE
Further Loc. Details

Date 20160826 08:15
Drainage

Upstream MH 295A **Rim-Invert** 0.0 ft **Grade-Invert** 0.0 ft **Rim-Grade** 0.0 ft
Downstream MH 291 **Rim-Invert** 0.0 ft **Grade-Invert** 0.0 ft **Rim-Grade** 0.0 ft


Use **Direction** Downstream **Joint Length** **Height** 8 in **Width**
Shape Circular **Flow Control** **Total Length** **Year Laid**
Material Asbestos Cement **Pre Cleaning** Jetting **Surveyed** 311.2 ft **Year Rehab**
Lining **Weather** **Purpose**
Location **Category**
Media/Tape # **Pressure**
Northing **Easting** **Elevation**
GPS Accuracy **Coordinate System**

Additional Info

Work Order

Project

DVS File C:\Users\Preferred Customer\Documents\My Muni Data\POUGHKEEPSIE CLEAN AND TV 2016\MH 295A_MH 291_160826_128.wmv



Pipe Graphic Report of
Database: POUGHKEEPSIE CLEAN AND TV 2016.mdb

PO #

Sheet # 128
Surveyor MANNY (07003732)
Street SEITZ TERRACE
City POUGHKEEPSIE
Further Loc. Details

Owner

Date 20160826 08:15
Drainage

Upstream MH 295A **Rim-Invert** 0.0 ft **Grade-Invert** 0.0 ft **Rim-Grade** 0.0 ft
Downstream MH 291 **Rim-Invert** 0.0 ft **Grade-Invert** 0.0 ft **Rim-Grade** 0.0 ft


Use **Direction** Downstream **Joint Length** **Height** 8 in **Width**
Shape Circular **Flow Control** **Total Length** **Year Laid**
Material Asbestos Cement **Pre Cleaning** Jetting **Surveyed** 311.2 ft **Year Rehab**
Lining **Weather** **Purpose**
Location **Category**
Media/Tape # **Pressure**
Northing **Easting** **Elevation**
GPS Accuracy **Coordinate System**

Additional Info

Work Order

Project

DVS File C:\Users\Preferred Customer\Documents\My Muni Data\POUGHKEEPSIE CLEAN AND TV 2016\MH 295A_MH 291_160826_128.wmv



Pipe Graphic Report of
Database: POUGHKEEPSIE CLEAN AND TV 2016.mdb

PO #

Sheet # 112
Surveyor MANNY (07003732)
Street JOHNS BOULEVARD
City POUGHKEEPSIE
Further Loc. Details

Owner

Date 20160825 09:00
Drainage

Upstream MH 300 **Rim-Invert** 0.0 ft **Grade-Invert** 0.0 ft **Rim-Grade** 0.0 ft
Downstream MH 299 **Rim-Invert** 0.0 ft **Grade-Invert** 0.0 ft **Rim-Grade** 0.0 ft


Use **Direction** Downstream **Joint Length** **Height** 8 in **Width**
Shape Circular **Flow Control** **Total Length** **Year Laid**
Material Clay Tile **Pre Cleaning** Jetting **Surveyed** 167.4 ft **Year Rehab**
Lining **Weather** **Purpose**
Location **Category**
Media/Tape # **Pressure**
Northing **Easting** **Elevation**
GPS Accuracy **Coordinate System**

Additional Info

Work Order

Project

DVS File C:\Users\Preferred Customer\Documents\My Muni Data\POUGHKEEPSIE CLEAN AND TV 2016\MH 300_MH 299_160825_112.wmv



Pipe Graphic Report of
Database: POUGHKEEPSIE CLEAN AND TV 2016.mdb

PO #

Sheet # 112
Surveyor MANNY (07003732)
Street JOHNS BOULEVARD
City POUGHKEEPSIE
Further Loc. Details

Owner

Date 20160825 09:00
Drainage

Upstream MH 300 **Rim-Invert** 0.0 ft **Grade-Invert** 0.0 ft **Rim-Grade** 0.0 ft
Downstream MH 299 **Rim-Invert** 0.0 ft **Grade-Invert** 0.0 ft **Rim-Grade** 0.0 ft


Use **Direction** Downstream **Joint Length** **Height** 8 in **Width**
Shape Circular **Flow Control** **Total Length** **Year Laid**
Material Clay Tile **Pre Cleaning** Jetting **Surveyed** 167.4 ft **Year Rehab**
Lining **Weather** **Purpose**
Location **Category**
Media/Tape # **Pressure**
Northing **Easting** **Elevation**
GPS Accuracy **Coordinate System**

Additional Info

Work Order

Project

DVS File C:\Users\Preferred Customer\Documents\My Muni Data\POUGHKEEPSIE CLEAN AND TV 2016\MH 300_MH 299_160825_112.wmv



Pipe Graphic Report of
Database: POUGHKEEPSIE.mdb

PO #

Sheet # 126 **Owner**
Surveyor RICH (06022759)
Street HAGANTOWN EASEMENT
City POUGHKEEPSIE

Date 20141216 10:06
Drainage

Further Loc. Details

Upstream MH7	Rim-Invert 0.0 ft	Grade-Invert 0.0 ft	Rim-Grade 0.0 ft
Downstream MH6	Rim-Invert 0.0 ft	Grade-Invert 0.0 ft	Rim-Grade 0.0 ft

Use	Direction Downstream	Joint Length	Height 8 in	Width
Shape Circular	Flow Control	Total Length	Year Laid	
Material Cast Iron	Pre Cleaning Jetting	Surveyed 95.6 ft	Year Rehab	
Lining	Weather	Purpose		
Location		Category		

Media/Tape #	Easting	Elevation	Pressure
Northing	Coordinate System		
GPS Accuracy			

Additional Info

Work Order **Project**
DVS File C:\ Documents and Settings\ User\ My Documents\ My Muni Data\ POUGHKEEPSIE\
 MH7_MH6_141216_126.wmv

